


FIG. 1

00000000000000000000000000000000






FIG. 2**FIG. 3**

FIG. 4

SCRATCH PREVENTION PANEL STRUCTURE

FIG. 5 (PRIOR ART)

CONVENTIONAL PANEL STRUCTURE

FIG. 6**FIG. 7**

TURNING-OVER OCCURS
AT VERTICAL SLIT PORTION






FIG. 8 (PROIR ART)**FIG. 9**


FIG. 10



FIG. 11**FIG. 12**

FIG. 13